


61-100 Coolant Level Sensor

Our Heavy Duty Customers have been relying on the Pollak® 61-100 Coolant Level Sensor as a direct-fit OE replacement for failed coolant level sensors.



Tech Tip

When the coolant tank or sensor fail it can cause coolant to wick down the harness. Pollak® offers a high-quality solution for replacing a failed or coolant-contaminated electrical connector.

65-115P Electrical Connector

- Utilizing high grade materials to ensure peak conductivity and perfect connections
- Decades of industry leading research and development focused on meeting the technician's needs
- With industry leading expertise, when original equipment fails our products are designed to fix the inherent failure issues

